



**REPLACEMENT OIL PUMP
DRIVE SHAFT
P/N 22070 & 22090**

For 400 cu in. Chevy blocks, the hole in the block and rear main cap that the oil pump shaft goes through must be opened up to 9/16" diameter. Failure to do so could result in severe engine damage.

***For Technical Assistance, Call Moroso's Tech Line at
(203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time***

**MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906**

Visit Us At www.moroso.com