



PART # 24506

Note: Use with a Ford Motorsports HV Oil pump P/N M-6600-D2 on a 302 C.I. Eng. Secure with (2) 3/8-16-1" screws.

Note: Replace the driver's side No. 2 and No. 4 main cap bolts with (1) Ford SVO bolt P/N C6TZ-6345-C which has a taller hex head with a 5/16-24 tapped hole on top. If using stud kit, pickup stud not required.

For Technical Assistance, Call Moroso's Tech Line at (203) 458-0542, 458-0546 8:30am – 5:00pm Eastern Time

**MOROSO PERFORMANCE PRODUCTS, INC
80 CARTER DR • GUILFORD, CT 06437
Phone: (203) 453-6571 • Fax: (203) 453-6906**

Visit Us At www.moroso.com